

Compressor for screen printer

The Serbian customer bought an automatic screen printing machine requiring technical documentation: which compressor capacity is optimal , no experience , 50 lit, 100 lit or more?

He did not understand GAS consumption 13L/pcs??what is 3p?

3p*735w=2.5kw 0.8MPa 100 lit