

METALS INTERNATIONAL LIMITED

金属国际有限公司

1068 Wuzhong Road, Shanghai 201103, P.R. China Tel: +86-21-60900836/60900837 Fax: +86-21-60900838

P.O. No.JAM11031

Email: metalsintl@klsteel.com www.klsteel.com

INSPECTION REPORT

Project Name: Lilydale Pipeline

Project, Australia

Issued on: Jun 10th, 2011

Inspection Time: May 20th-Jun 2ed, 2011

Inspection FBE Coated HFI-ERW Line Pipes Subject:

API 5L X56M PSL 2/AS 2885-1

Specification: Lin Gaojie Inspector: Stamp No: AS 3862

Visit Summary:

Scope of Inspection

- Ultrasonic Testing verification
- Mechanical Testing verification
- Coating verification
- Packaging, marking and storing inspection.
- Part photo service.

Results of inspection to Lilydale Pipeline Project

Process Verification

Ultrasonic Testing verification

The customer had verified Ultrasonic Testing.

Photo attachment as below





Verifying Ultrasonic Testing

Mechanical Testing verification

The customer had verified Mechanical Testing. And the following is for DWTT. Photo attachment as below

Page 1 of 4



Metals International Limited

金属国际有限公司

1068 Wuzhong Road, Shanghai 201103, P.R. China Tel: +86-21-60900836/60900837 Fax: +86-21-60900838 www.klsteel.com

Email: metalsintl@klsteel.com





Page 2 of 4

Samples





Verifying DWTT

3. Coating verification

The customer had verified Coating at coating plant.

Photo attachment as below





Verifying Coating



Metals International Limited

金属国际有限公司

1068 Wuzhong Road, Shanghai 201103, P.R. China Tel: +86-21-60900836/60900837 Fax: +86-21-60900838

www.klsteel.com Email: metalsintl@klsteel.com







Verifying Coating

- Packaging, marking and storing inspection
- 1) The mill had fixed end protectors on both of pipe ends;
- 2) The marking and shipping mark was right;
- 3) The pipes were stored in the stacking which was clean and covered with rubber.

Photo attachment as below





Round Color Band per thickness

Stacking



METALS INTERNATIONAL LIMITED

金属国际有限公司

1068 Wuzhong Road, Shanghai 201103, P.R. China
Tel: +86-21-60900836/60900837 Fax: +86-21-60900838
www.klsteel.com Email: metalsintl@klsteel.com

Page 4 of 4





Handling

Shipping

Review of Documentation:

Raw Material Testing Report
UT Test on coils, Welded Seams and Full Body
Hydrotest Report
Pipe Chemical and Physical Testing Report
Mill Test Certificate
Cathodic Bonded Test Report
Thickness Test Records

Remark

The inspection results shows that the pipes are in full conformity with the specifications and client's technical requirements.